REPORT DOCUMENTATION PAGE

Form Approved
OMB No. 0704-0188

1. REPORT DATE *(DD-MM-YYYY)*	2. REPORT TYPE	3. DATES COVERED *(From - To)*
03-01-2004	Technical Paper (View Graph)	

4. TITLE AND SUBTITLE

Monitoring Micro-Structural Evolution and Crack Formation in a Solid Propellant under Incremental Strain Condition – Using Digital Radiograph X-Ray Techniques

5a. CONTRACT NUMBER
F04611-99-C-0025

5b. GRANT NUMBER

5c. PROGRAM ELEMENT NUMBER

6. AUTHOR(S)

C. T. Liu, Lee M. Klynn, Jay D. Thompson

5d. PROJECT NUMBER
2302

5e. TASK NUMBER
0378

5f. WORK UNIT NUMBER

7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES)

ERC Incorporated
555 Sparkman Drive
Huntsville, AL 35816-0000

8. PERFORMING ORGANIZATION REPORT NUMBER

9. SPONSORING / MONITORING AGENCY NAME(S) AND ADDRESS(ES)

Air Force Research Laboratory (AFMC)
AFRL/PRSB
4 Draco Drive
Edwards AFB CA 93524-7160

10. SPONSOR/MONITOR'S ACRONYM(S)

11. SPONSOR/MONITOR'S NUMBER(S)
AFRL-PR-ED-VG-2004-049

12. DISTRIBUTION / AVAILABILITY STATEMENT

Approved for public release; distribution unlimited.

13. SUPPLEMENTARY NOTES

JANNAF Nondestructive Evaluation Subcommittee Meeting (NDES)
New Orleans, LA, 29 Mar – 02 Apr 2004

14. ABSTRACT

15. SUBJECT TERMS

16. SECURITY CLASSIFICATION OF:			17. LIMITATION OF ABSTRACT	18. NUMBER OF PAGES	19a. NAME OF RESPONSIBLE PERSON
					Linda Talon
a. REPORT	b. ABSTRACT	c. THIS PAGE	A	10	19b. TELEPHONE NUMBER *(include area code)*
Unclassified	Unclassified	Unclassified			(661) 275-5865

Monitoring Micro-Structural Evolution and Crack Formation in a Solid Propellant under Incremental Strain Condition-Using Digital Radiograph X-Ray Techniques

C. T. Liu
AFRL/PRSM
10 E. Saturn Blvd.
Edwards AFB CA 93524-7680

Lee M. Klynn & Jay D. Thompson
Lockheed Martin
Advanced Technology Center
3251 Hanover St.
Palo Alto, CA 91356

Objective

- **Monitor Micro-Structure Evolution, Damage process, and Crack Formation in a Solid Propellant.**

Testing Setup



X-Ray Images at Different Amounts of Stretch



0.0" stretch | 0.1" stretch | 0.2" stretch | 0.3" stretch | 0.4" stretch | 0.5" stretch

Uniaxial_sample3_comp.jpg

Test Sample #3

Difference X-Ray Images of the Change from One Stretch to the Next



Sample3_diff_comp.jpg

Difference Images for Sample #3

Section Strain as a Function of Applied Strain



Histogram of X-Ray Intensity as Function of the Applied Strain at the Crack Location



ε = 0%



ε = 27%



ε = 29%



Coefficient of Variation of X-Ray Intensity and Volume Dilatation as Functions of Applied Strain



Volume Dilatation as a Function of Applied Strain



Conclusions

- The degree of inhomogeneity of material's micro-structure and number of non-propagating cracks increase as the applied strain is increased.
- The rate of x-ray intensity increases very fast prior to the formation of a crack.
- At high applied strain levels, the strain distributions are highly non-uniform.
- A good correlation exists between the dilatations measured by x-ray technique and dilatometer.
- X-ray technique is a promising method to monitor micro-structure change and crack formation in solid propellants.